



Product Release Notes

ThunderLink® NQ/NS 3402/3401/3102/3101 Release 1.0.17 - Windows

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink NQ 3402/3401 and NS 3102/3101, version, which was released on 12/01/17. This information pertains to the Windows 10, 8.1 and 7.

2. Changes

- **Version 1.0.17 (Released 12/01/16)**
 - **New Features, Enhancements and Changes**
 - Initial release for the ThunderLink NS 3102/3101
- **Version 1.0.17 (Released 10/10/16)**
 - **New Features, Enhancements and Changes**
 - Initial release for the ThunderLink NQ 3402/3401

3. Known Issues/Advisements

1. Unplugging the TLNQ-34xx while the computer is sleeping or hibernating in combination with the MS iSCSI initiator is being used may cause a blue screen when the computer is awakened and the TLNQ is left unplugged.
2. Microsoft Hotfix KB2471472 Required for Thunderbolt Hot Plugging in Windows 7

4. Affected Products

Product Name	SKU
ThunderLink NQ 3401(QSFP+)	TLNQ-3401-D00/DE0
ThunderLink NQ 3402(QSFP+)	TLNQ-3402-D00/DE0
ThunderLink NS 3101(SFP+)	TLNQ-3101-D00/DE0
ThunderLink NS 3102(SFP+)	TLNQ-3102-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@atto.com