



ATTO Technology, Inc.

# Product Release Notes

## Celerity 16Gb Fibre Channel Release v1.40– Mac OS X

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the Celerity 16Gb Fibre Channel adapter product v1.40 that was released on 8/06/2015. This information pertains to the Mac OS X 10.6.x and later.

### 2. Changes

---

- **Version 1.40 (Released 8/06/2015)**
  - **New Features/Enhancement**
    - Added support for 10.11
    - Improved system resource utilization when using event logging services
    - Addressed OSX handling issue that could lead to I/O errors
    - Implemented T10-PI management improvements
    - Fixed a max transfer size processing issue
  - **Supported OS**
    - Mac OS X 10.6
    - Mac OS X 10.7
    - Mac OS X 10.8
    - Mac OS X 10.9
    - Mac OS X 10.10
    - Mac OS X 10.11
- **Version 1.35 (Released 3/16/2015)**
  - **Note:** It is recommended that firmware dated 03/16/2015 be utilized with this driver release.
  - The following apply to driver v1.35
  - **New Features/Enhancements**
    - Addressed an event logging issue.
    - Addressed a timing issue when mounting volumes.
    - Fixed an issue of seeing LUNs in a direct attached environment.
- **Version 1.31 (Released 1/27/2015)**
  - **Note:** It is recommended that firmware dated 08/14/2014 be utilized with this driver release.
  - The following apply to driver v1.31
  - **New Features/Enhancements**
    - Fixed a resource leak issue.
    - Addressed an I/O response underrun
- **Version 1.30 (Released 10/30/2014)**
  - **Note:** It is recommended that firmware dated 08/14/2014 be utilized with this driver release.
  - The following apply to driver v1.30
  - **New Features/Enhancements**
    - Added support for Mac OS X 10.10
    - Addressed a firmware issue causing an error when querying a switch
    - Corrected an issue where HBAs failed to properly recover from a controller reset.
- **Version 1.25 (Released 08/28/2014)**
  - **Note:** It is recommended that firmware dated 08/14/2014 be utilized with this driver release.

- The following apply to driver v1.25
- **New Features/Enhancements**
  - Enhanced diagnostic capabilities with improved event logging
  - Improved CLI management capabilities
  - Added support for atreset
  - Added support for device display in atinfo
  - Addressed a potential kernel panic when drivers run out of IO resources
  - Addressed a potential kernel panic when a FC ThunderLink is present
- **Version 1.20 (Released 03/27/2014)**
  - **Note:** It is recommended that firmware dated 12/02/2013 be utilized with this driver release.
  - The following apply to driver v1.20
  - **New Features/Enhancements**
    - Corrected issue with Execution Throttle that could prevent I/O from being started.
- **Version 1.15 (Released 02/06/2014)**
  - **Note:** It is recommended that firmware dated 12/02/2013 be utilized with this driver release.
  - The following apply to driver v1.15
  - **New Features/Enhancements**
    - Added PCIe pause support for Thunderbolt hot plugging in OS X 10.9.
- **Version 1.10 (Released 10/15/2013)**
  - **Note:** It is recommended that firmware dated 4/10/2013 be utilized with this driver release.
  - The following apply to driver v1.10
  - **New Features/Enhancements**
    - Mac OS X Mavericks (10.9) Support.
    - Increased the maximum supported targets from 256 to 512.
    - Corrected an issue with read commands that falsely complete with a GOOD SCSI status.
- **Version 1.02 (Released 4/17/2013)**
  - **Note:** It is recommended that firmware dated 4/10/2013 be utilized with this driver release.
  - The following apply to driver v1.02
  - **New Features/Enhancements**
    - Implemented improvements for SAN Boot
    - Updated "--m" options for OS X 10.7 & later
- **Version 1.01 (Released 1/15/2013)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - The following apply to driver v1.01
  - **New Features/Enhancements**
    - Changed the default Execution Throttle to 255 (disabled)
    - Implemented interrupt coalescing
    - Fixed event Log messages so lost frames report with the correct error code
    - Corrected an issue that could result in devices not being found after waking from sleep
- **Version 1.00 (Released 11/08/2012)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - The following apply to driver v1.00
  - **New Features/Enhancements**
    - Initial release of Mac drivers for the Celerity 16Gb FC adapters
  - **Supported OS**
    - Mac OS X 10.8
    - Mac OS X 10.7
    - Mac OS X 10.6

### 3. Known Issues/Advisements

---

- Multiple direct connections to a Xyratex drive array do not work.

- Celerity quad-channel (FC-164E) is not support on Mac operating system.

#### 4. Affected Products

---

Product Name	SKU
Celerity FC 161E	CTFC-161E-000
Celerity FC 162E	CTFC-162E-000

#### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit <https://www.attotech.com/support/> for hours of operation.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)