



## Celerity 16Gb Fibre Channel Release v1.30 – Windows Microsoft Certified Drivers

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the Celerity 16Gb Fibre Channel adapter product v1.30 that was released on 01/21/2016. This information pertains to the Windows 10, 8.1, 8, 7, 2012 R2, 2012, 2008 R2, 2008 R2, and 2008.

### 2. Changes

---

- **Version 1.30 (Released 01/21/2016)**
  - **Note:** It is recommended that the latest firmware available on ATTO website be utilized with this driver release.
    - Updates to events that are logged
    - Resolved an error that could result in an exchange used for a nameserver request completing for a port logged out
  - **New Features & Enhancements**
    - Microsoft Certified package for Windows 10
  
- **Version 1.26 (Released 10/15/2015)**
  - **Note:** It is recommended that the latest firmware available on ATTO website be utilized with this driver release.
  - **New Features & Enhancements**
    - Microsoft Certified package for Windows 10
  
- **Version 1.25 (Released 8/06/2015)**
  - **Note:** It is recommended that the latest firmware available on ATTO website be utilized with this driver release.
  - **New Features & Enhancements**
    - Added support for Windows 10
    - Implemented T10-PI management improvements
    - Integrated miscellaneous bug fixes
  
- **Version 1.20 (Released 3/16/2015)**
  - **Note:** It is recommended that the latest firmware be utilized with this driver release.
  - The following apply to driver v1.20
  - **New Features & Enhancements**
    - Fixed a timing issue when mounting a volume.
    - Addressed an issue with seeing LUNs in a direct attached environment.
  
- **Version 1.16 (Released 1/27/2015)**
  - **Note:** It is recommended that the latest firmware be utilized with this driver release.
  - The following apply to driver v1.16
  - **New Features & Enhancements**
    - Corrected an exchange leak issue.
  
- **Version 1.15 (Released 10/30/2014)**

- **Note:** It is recommended that the latest firmware be utilized with this driver release.
- The following apply to driver v1.15
- **New Features & Enhancements**
  - Corrected a resource and performance issue concerning the number of logins being generated by NPIV ports.
  - Addressed a firmware issue causing an error when querying a switch
  - Addressed an issue where HBAs failed to properly recover from a controller reset.
  - Increased the number of Registry parameter NumRequests to 3000
- **Version 1.11 (Released 10/30/2014)**
  - **Note:** It is recommended that the latest firmware be utilized with this driver release.
  - The following apply to driver v1.11
  - **New Features & Enhancements**
    - Microsoft Certified Drivers for Windows 8, 8.1 (x86, x64) & 2012, 2012 R2 (x64)
- **Version 1.10 (Released 07/08/2014)**
  - **Note:** It is recommended that the latest firmware be utilized with this driver release.
  - The following apply to driver v1.10
  - **New Features & Enhancements**
    - Improved IOPS performance
    - Enhanced the device display in atinfo
    - Added support for atreset
    - Addressed an issues where Windows drivers cannot interpret older Windows driver eventlogs
- **Version 1.07 (Released 03/27/2014)**
  - **Note:** It is recommended that the latest firmware be utilized with this driver release.
  - The following apply to driver v1.07
  - **New Features & Enhancements**
    - Corrected issue with Execution Throttle that could prevent I/O from being started
    - Added support for Windows 8.1 (x86, x64) and Server 2012 R2 (x64)
- **Version 1.06 (Released 02/06/2014)**
  - **Note:** It is recommended that the latest firmware be utilized with this driver release.
  - The following apply to driver v1.06
  - **New Features**
    - Improved LinkDown timeout resolution.
    - Added SCSI Write 12 to T10-DIF capable commands.
    - Register service parameters in FLOGI along with PLOGI.
    - Increased the retry timer to 150ms from 100ms.
    - Improved how a port database entry is initialized.
- **Version 1.05 (Released 11/25/2013)**
  - **Note:** It is recommended that firmware dated 4/10/2013 be utilized with this driver release.
  - The following apply to driver v1.05
  - **New Features**
    - Increased the maximum supported targets from 256 to 512.
    - Added uninstall functionality to the driver installer.
    - Modified driver to handle read commands with missing or corrupted data frames that complete with a GOOD SCSI status.
    - Updated driver when NPIV is disabled to always attempt to log into ports on a fabric.
  - **Supported OS**
    - Windows 8 (x86, x64)
    - Windows 7 (x86, x64)
    - Windows Server 2012 (x86, x64)
    - Windows Server 2008 R2 (x86, x64)
    - Windows Server 2008 (x86, x64)
- **Version 1.03 (Released 4/17/2013)**
  - **Note:** It is recommended that firmware dated 4/10/2013 be utilized with this driver release.

- The following apply to driver v1.03
- **New Features**
  - This driver release has passed Microsoft's HCK compatibility tests and is listed on the Windows Certified Products List for Windows 7, 8, Server 2008 R2 and 2012
  - Support was added for Windows 2012 Hyper-V
  - Corrected a timing issue with Task Management commands
  - Fixed a blue screen that occurred when coming out of hibernation
  - Updated HBA API Get Port Statistics to return accurate time value
- **Supported OS**
  - Windows 8 (x86, x64)
  - Windows 7 (x86, x64)
  - Windows Server 2012 (x86, x64)
  - Windows Server 2008 R2 (x86, x64)
  - Windows Server 2008 (x86, x64)
- **Version 1.02 (Released 1/15/2013)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - The following apply to driver v1.02
  - **New Features**
    - Added support for the quad port Celerity 16Gb Fibre Channel Host Adapter (164E)
    - Changed the default Execution Throttle to 255 (disabled)
    - Implemented interrupt coalescing
    - Implemented NPIV for Windows 2008 and later
    - Data transfer errors no longer cause the command to be aborted without allowing the upper layer to send a response in Target Mode
    - Fixed event Log messages so lost frames report with the correct error code
    - Code that set the Disable Laser GPIO pin to a known state was removed because it seemed to be causing a laser TX\_FAULT to occur when coming out of sleep
- **Version 1.01 (Released 11/8/2012)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - The following apply to driver v1.01
  - **New Features**
    - SAN Boot is now supported
    - T10 DIF now can be enabled in Windows
    - Fibre Channel Link Down Timeout is now operational
    - The Port Database is now sorted so devices show up in the same order across reboots
    - Enhanced the PCIe speed capability back up to Gen 3 if it had been lowered by placing the card in another platform
    - Addressed an unexpected driver removal when in loop mode
    - Fixed an issue where the HBA API Get Port Stats would hang
  - **Supported OS**
    - Windows 8 (x86, x64)
    - Windows 7 (x86, x64)
    - Windows Vista (x86, x64)
    - Windows XP (x86, x64)
    - Windows Server 2012 (x86, x64)
    - Windows Server 2008 R2 (x86, x64)
    - Windows Server 2008 (x86, x64)
    - Windows Server 2003 (x86, x64)
- **Version 1.00 (Released 9/28/2012)**
  - **Note:** It is recommended that firmware dated 9/24/2012 be utilized with this driver release.
  - The following apply to driver v1.00
  - **New Features**
    - Initial release of Windows drivers for the Celerity 16Gb FC adapters
  - **Supported OS**
    - Windows 8 (x86, x64)
    - Windows 7 (x86, x64)
    - Windows Vista (x86, x64)

- Windows XP (x86, x64)
- Windows Server 2012 (x86, x64)
- Windows Server 2008 R2 (x86, x64)
- Windows Server 2008 (x86, x64)
- Windows Server 2003 (x86, x64)

### 3. Known Issues/Advisements

---

- When connecting directly to a disk drive while the topology is set to P2P Preferred (or AL preferred) the device may not be found with auto-topology. If this happens adjust topology setting.
- Arbitrated Loop is not support by the 16Gb Fibre Channel - the industry specification has not been finalized.
- The minimum requirement for StorPort drivers is Windows XP or 2003 SP2.
- An Unsigned Driver warning will appear when installing on Vista and 2008. This is expected behavior as Microsoft has not issued a Windows Update with their latest Root Certificate. Subsequent installs should not produce the warning.
- Multiple direct connections to a Xyratex drive array do not work.
- If the system will not boot in a MSI 277A-GD80 motherboard and the System BIOS PCI ROM Priority is set for EFI Compatible ROM, set the System BIOS PCI ROM Priority setting to Legacy ROM.
- System will not boot when card is installed in an Intel Grosse Point machine.

### 4. Affected Products

---

Product Name	SKU
Celerity FC 161E	CTFC-161E-000
Celerity FC 162E	CTFC-162E-000
Celerity FC 164E	CTFC-164E-000

### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit <https://www.attotech.com/support/> for hours of operation.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)