



ExpressSAS Host Adapter 12Gb Flash Bundle v150521

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ExpressSAS 12Gb Host Adapter flash bundle package, version 150521, which was released on May 27, 2015. This information pertains to the flash bundles and EFI utility associated with the ExpressSAS 12Gb Host Adapter products.

2. Changes

- **Version 150521/EFI v1.15 (Released 05/27/2015)**
 - **New Features, Enhancements and Changes**
 - Incorporate firmware 3.07.73.
 - Devices in expander topologies with a link rate not applicable to the NVRAM setting are no longer presented to the system.
 - Add support for spinning up SATA drives that have PUIS enabled.
 - No longer set ordered task attributes to work around a problem with unsupported SES devices.
 - Fixed a timing window that could cause a 6Gb SATA drive to not be discovered.
 - Fixed SGPIO operation on the H1208.
 - Fixed an issue where a SATA I/O timeout occurred if a protocol error prevented a retry of a command.
 - The EFI driver is now signed to support UEFI Secure Boot.

- **Version 141113/EFI v1.10 (Released 12/16/2014)**
 - **New Features, Enhancements and Changes**
 - Incorporated firmware 3.07.66.
 - Added support for the H1244, H1248 and H1288.
 - Fixed an issue with the driver's device scan where devices would be blocked from the system if they didn't have a valid LUN 0.
 - In the presence of multiple logical SAS ports, when the controller is reset, fixed an issue that could result in the SAS ports not containing the correct PHYs. This could result in improper SAS discovery or detection of read-only ports.
 - Fixed an issue that could cause a RAID group to disappear after a controller reset.
 - Fixed an issue that could cause the adapter to go degraded before initialization is complete.
 - Fixed a port reset issue that could cause newly attached devices to not be discovered.
 - Fixed an issue that could cause discovery to be blocked forever if discovery command timeout recovery required a controller reset.
 - All discovery operations in flight are correctly aborted if a controller reset occurs.
 - I/O connection errors due to incomplete expander routing are now retried.
 - Increased the discovery command timeout to account for slow SATA SSDs.
 - Fixed an issue with aborting timed out discovery requests.

- **Version 140730/EFI v1.05 (Released 8/1/2014)**
 - **New Features, Enhancements and Changes**
 - Incorporated firmware 3.07.40.
 - Resolved an issue regarding correct interpretation of descriptor based sense data during the driver's device scan.
 - Increased the wait time for devices to become ready from 30 to 60 seconds.
- **Version 140423/EFI v1.00 (Released 5/2/2014)**
 - **New Features, Enhancements and Changes**
 - Initial release for the H1280, H1208, H12F0 and H120F.

3. Known Issues/Advisements

- A corrupted data frame transmitted by a device and recovered by Transport Layer Retries may be completed with an I/O error to the host application.

4. Affected Products

Product Name
ExpressSAS H1208
ExpressSAS H1280
ExpressSAS H12F0
ExpressSAS H120F
ExpressSAS H1244
ExpressSAS H1248
ExpressSAS H1288

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com