



ATTO Technology, Inc.

Product Release Notes

ExpressSAS 12Gb SAS/SATA HBA Release v1.05 - VMware

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ExpressSAS 12Gb HBA product line driver version 1.05 that was released on December 15, 2014. This information pertains to VMware ESXi Server (vSphere) 5.5.

2. Changes

- **Version 1.05 (Released 12/15/2014)**

- **Note:** It is recommended that firmware dated 5/21/15 be used with this driver release.
- **New Features, Enhancements and Changes**
 - Added support for the H1244, H1248 and H1288.
 - Fixed several issues with recovering a device if task management fails.
 - Fixed an issue with the driver's device scan where devices would be blocked from the system if they didn't have a valid LUN 0.
 - In target mode, when configured for multiple targets, fixed an issue with task management handling that could abort I/O for targets not applicable to the task management.
 - Fixed an issue that could prevent the OS from seeing devices that swapped positions in the topology.
 - Fixed an issue that could cause devices to not be reinserted into a RAID group correctly. This could occur during power management cycles or during cable pull, or replug, within the link down timeout period.
 - Fixed an issue that could cause RAID groups to be degraded when resuming from power management.
 - In the presence of multiple logical SAS ports, when the controller is reset or resumes from power management, fixed an issue that could result in the SAS ports not containing the correct PHYs. This could result in improper SAS discovery or detection of read-only ports.
 - Fixed an issue that could cause a RAID group to disappear after a controller reset.
 - Fixed an issue that could cause the adapter to go degraded before initialization is complete.
 - Fixed a port reset issue that could cause newly attached devices to not be discovered.
 - Fixed an issue that could cause discovery to be blocked forever if discovery command timeout recovery required a controller reset.
 - All discovery operations in flight are correctly aborted if a controller reset occurs.
 - I/O connection errors due to incomplete expander routing are now retried.
 - Increased the discovery command timeout to account for slow SATA SSDs.
 - Fixed an issue with aborting timed out discovery requests.
 - Interpret descriptor based sense data correctly during the driver's device scan.
 - Update device table so that the VMware vSphere web client identifies our devices using their correct names.

- **Version 1.01 (Released 5/21/2014)**
 - **Note:** It is recommended that firmware dated 4/23/2014 be used with this driver release.
 - **New Features, Enhancements and Changes**
 - This is the initial release of the ExpressSAS 12G HBA driver for VMware.

3. Known Issues/Advisements

- None

4. Affected Products

Product Name
ExpressSAS H1208
ExpressSAS H1280
ExpressSAS H12F0
ExpressSAS H120F

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com