



ExpressSAS 6Gb RAID macOS® Driver Release v3.76

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to **ExpressSAS 6GB RAID** product, **macOS** driver version **3.76** that was released on **07/12/2016**.

2. Changes

- **Version 3.76 (Released 07/12/2016)**
 - **It is recommended that firmware version 190125 be utilized with this driver release.**
 - **New Features**
 - Added support for macOS Sierra
 - Resolved a rare issue where the driver could crash when running heavy I/O.
- **Version 3.75 (Released 03/18/2016)**
 - **It is recommended that firmware dated 160316 be used with this driver release.**
 - **New Features**
 - Added feature that attempts to recover a firmware core dump when the heartbeat fails on firmware.
 - Modified logging features to limit the size of the event log. Up to five 50 MB log files will be created.
 - Updated code signing to support future versions of OS X.
- **Version 3.70 (Released 12/16/2015)**
 - **It is recommended that firmware dated 151211 be used with this driver release.**
 - **New Features**
 - Added feature that attempts to recover a firmware core dump when the heartbeat fails on firmware.
 - Modified event log messages for firmware faults to be more descriptive.
 - Modified the method by which driver events are consumed by the ConfigTool.
- **Version 3.65 (Released 09/30/2015)**
 - **It is recommended that firmware dated 150604 be used with this driver release.**
 - **New Features**
 - Added support for OS X 10.11
- **Version 3.60 (Released 06/10/2015)**
 - **It is recommended that firmware dated 150604 be used with this driver release.**
 - **New Features**
 - Made changes to detect when the firmware has been reset before the driver has loaded and attempt to save the core dump and recover the firmware.

- **Version 3.55 (Released 10/24/2014)**
 - **It is recommended that firmware dated 141023 be used with this driver release.**
 - **New Features**
 - Fixed a potential driver crash if the adapter is reset when driver resources are exhausted.
 - Resolved a rare instance where RAID group commands may be improperly formatted during an adapter reset.

- **Version 3.50 (Released 8/5/2014)**
 - **It is recommended that firmware dated 140713 be used with this driver release.**
 - **New Features**
 - Added a service to always log all driver output to a file that is collected by Config Tool diagnostics. The driver name and version are logged on every boot. The log file is not deleted when the driver is uninstalled.
 - Driver events are written to the OS X system log. By default, only fatal events are reported. The event log mask can be changed to log additional events. See driver readme file for more information.
 - Updated the driver so the required system drivers are loaded earlier.
 - Added discovery of RAID50 / RAID60 groups for firmware that support them.
 - Fixed a memory leak when the driver is unloaded and reloaded within 60 seconds.
 - General speed improvements for application interfaces. For example, large numbers of devices should display faster in *atinfo*.

- **Version 3.25 (Released 4/2/2014)**
 - **It is recommended that firmware dated 140327 be used with this driver release.**
 - **New Features**
 - Added PCIe pause support for Thunderbolt hot plugging in OS X 10.9.
 - Enhanced event logs when the driver resets the firmware. Now indicates why the driver reset the firmware.

- **Version 3.20 (Released 10/15/2013)**
 - **It is recommended that firmware dated 130625 be used with this driver release.**
 - **New Features**
 - Mac OS X Mavericks (10.9) Support.
 - Added support for Frey B3 chips.

- **Version 3.15 (Released 6/27/2013)**
 - **It is recommended that firmware dated 130625 be used with this driver release.**
 - **New Features**
 - Added event logging to discovery process.
 - Pass through devices in firmware versions prior to 3.00 are no longer discovered. This prevents data corruption.

- **Version 3.10 (Released 3/12/2013)**
 - **It is recommended that firmware dated 130304 be utilized with this driver release.**
 - **New Features**
 - Pass through devices are persistently mapped to prevent data corruption.
 - Corrected an issue with the event logging that would cause the wrong time to be logged after the system was put to sleep. Note that both the driver and event logging application have changed and are not compatible with previous releases.
 - We now notify the firmware when the driver is shutting down.
 - Added support for the *atsasphy* and *atsastop* CLI tools.
 - Added support for additional firmware based functionality in the *atinfo* and *attrace* CLI tools.
 - Added support for the SMP API.
 - Added support for CSMI.
 - Improved the device scan time for CLI tools such as *atinfo*.
 - Return a zero size file if the firmware core dump is not present.
 - Added support for reading the SAS address of front-end devices.

- Corrected an issue that could prevent the event log from displaying the entire RAID group name.
- **Version 3.05 (Released 10/11/2012)**
 - **It is recommended that firmware dated 130927 be utilized with this driver release.**
 - **New Features**

Updated the memory allocation for x64 platforms for compatibility with OS X 10.8.2 and later.

 - Added support for Frey B2 chips.
 - Made enhancements to send a notification that the firmware has been reset when coming out of power management.
 - Improved the device polling based on the Device Wait Time and Count settings to prevent device thrashing on power up and sleep recovery.
- **Version 3.04 (Released 8/24/2012)**
 - **It is recommended that firmware dated 120824 be utilized with this driver release.**
 - **New Features**
 - Added support for extracting a firmware core dump using the *atrace* CLI tool.
 - Corrected a firmware issue during performance and health monitoring.
- **Version 3.03 (Released 7/25/2012)**
 - **It is recommended that firmware dated 120611 be utilized with this driver release.**
 - **New Features**
 - Mac OS X Mountain Lion (10.8) Support.
 - This driver version does not support OS X Tiger (10.4), or earlier.
 - Corrected an intermittent issue that caused a kernel panic when waking from sleep.
- **Version 3.02 (Released 4/23/2012)**
 - **It is recommended that firmware dated 120217 be utilized with this driver release.**
 - **New Features**
 - Several enhancements have been made throughout the driver to resolve Thunderbolt hot plugging and sleep issues.
 - The minimum device wait time when resuming from sleep was increased from 5 to 15 seconds.
 - When resuming from sleep, device state changes are ignored until the device wait time has elapsed.
- **Version 3.01 (Released 2/22/2012)**
 - **It is recommended that firmware dated 120217 be utilized with this driver release.**
 - **New Features, Enhancements and Changes**
 - The fan controller daemon was updated to print a message and use default settings if an error occurs while reading the plist file from the disk.
 - The installer has been updated to set the correct permissions for the /Library/LaunchDaemons directory in OS X 10.5.8, and earlier.
 - Added support for the *atreset* CLI tool.
 - Corrected an issue where resources are exhausted while command coalescing.
- **Version 3.00 (Released 12/15/2011)**
 - **It is recommended that firmware dated 111215 be utilized with this driver release.**
 - **New Features**
 - Thunderbolt hot plugging is supported.
 - Added MSI support for 64-bit platforms.
 - The fan controller daemon was updated to function correctly on Xserve systems.
 - Several enhancements have been made to chip reset processing.
 - Enhancements have been made to error recovery and task management while using command coalescing.
 - Report which type of boot image is present on the card with Configuration Tool version 4.02 and later (BIOS, EFI 32-bit or EFI 64-bit).
- **Version 2.10 (Released 06/29/2011)**

- **It is recommended that firmware dated 110622 be utilized with this driver release.**
- **New Features**
 - We now set the default fan controller speed to 1500 RPM on all systems. This speed can also be set by the user via the fan controller daemon.
 - The driver to firmware communication mechanism has been changed. Driver v2.10, or later, is required to support firmware v2.50, and later. Additionally, the v2.10 driver supports earlier firmware versions from v2.00 up through v2.20.
 - The maximum transfer size value has been lowered to 4MB.
 - When resuming from sleep, the driver now waits two seconds before accessing the hardware to give the firmware adequate time to initialize.
- **Version 2.07 (Released 06/10/2011)**
 - **It is recommended that firmware dated 110418 be utilized with this driver release.**
 - **New Features**
 - Mac OS X Lion Support
 - R60F, R608 and R644 support virtual SES.
 - Added a property to enable the driver in Thunderbolt topologies.
 - This version is included on the OS X Lion DVD.
- **Version 2.06 (Released 03/25/2011)**
 - **It is recommended that firmware dated 110325 be utilized with this driver release.**
 - **New Features**
 - Increased performance for transactional and streaming applications.
 - Improved handling and discovery of drives during system reboot and when drives are pulled or reset.
 - Expanded reporting for disk drive Vendor ID.
 - NCQ is now enabled by default.
 - Resolved various, minor incident fixes to improve overall performance
- **Version 2.05 (Released 02/16/2011)**
 - **It is recommended that firmware dated 111102 be utilized with this driver release.**
 - **New Features**
 - Performance improvements in IOPs and MB/s applications.
 - CacheAssure™ performance improvements when in High Protection mode.
 - SAS Multiplexing implemented. This enables the user to achieve performance improvements with 6Gb RAID when using slower 3Gb drives.
 - Improved compatibility between the operating systems range of physical memory and the physical memory of the hardware.
 - Increased the default scatter/gather list size to 512 bytes.
 - Enhanced compatibility and stability on PowerPC systems.
- **Version 2.01 (Released 11/30/2010)**
 - **It is recommended that firmware dated 101119 be utilized with this driver release.**
 - **New Features**
 - Enhanced communication with the SMC controller in a fan controller.
- **Version 2.00 (Released 9/22/2010)**
 - **It is recommended that firmware dated 100917 be utilized with this driver release.**
Note: "Any upgrade from a previous version to 2.00 for the driver and firmware must be done in a specific order. Version 2.00 firmware must be updated first with a flash bundle using the ATTO Configuration Tool. Once the new firmware is flashed, "DO NOT REBOOT," the 2.00 driver should be loaded. Your system will appear to freeze for up to three minutes while the new driver is loaded. A reboot is required to use the new update."
 - **New Features**
 - Initial Release and added support for the R60F.
 - The driver to firmware communication mechanism has been improved. Driver versions 2.00 and later are only supported with version 2.00 and later firmware.
 - The fan controller daemon was updated to enhance support of MacPro5.1 systems.

- **Version 1.00 (Released 5/21/2010)**
 - **It is recommended that firmware dated 100520 be utilized with this driver release.**
 - **New Features**
 - Initial release for the R644, R680 and R608.

3. Known Issues/Advisements

- Occasionally, ExpressSAS R6xx RAID adapters installed in a Thunderbolt expansion chassis may experience a loss of connection to the host. This condition can be resolved with a cold system boot.
- “Deep” sleep is supported only on Intel Macs. PowerPC Macs will sleep, but not “deep” sleep, so the sleep light will not pulsate. The only side effect is that when PowerPC systems are put to sleep, the fan speed will increase to the max until the system is awakened.

4. Affected Products

Product Name	SKU
ExpressSAS R644 RAID Adapter	ESAS-R644-000
ExpressSAS R680 RAID Adapter	ESAS-R680-000
ExpressSAS R608 RAID Adapter	ESAS-R608-000
ExpressSAS R60F RAID Adapter	ESAS-R60F-000
ExpressSAS R644 RAID Adapter with CacheAssure	ESAS-R644-C00
ExpressSAS R680 RAID Adapter with CacheAssure	ESAS-R680-C00
ExpressSAS R608 RAID Adapter with CacheAssure	ESAS-R608-C00
ExpressSAS R60F RAID Adapter with CacheAssure	ESAS-R60F-C00

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO’s goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com