



ThunderLink™ FC 1082 Release v1.01 - Windows®

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 1082 Desklink™ Device, version 1.01, which was released on 07/17/13. This information pertains to Microsoft Windows Operating System including Windows 7, 8, Server 2008 R2 (x64 only) and 2012 platforms.

2. Changes

- **Version 1.01 (Released 07/17/13)**
 - **New Features, Enhancements and Changes**
 - Initial release for the ThunderLink FC 1082 Desklink Device.
 - The flash process has been updated to avoid potential issues during flashing.
 - Resolved an issue in target mode to correctly send ABTS Accept frames.
 - Resolved NumSest discovery failure.
 - Added ability to set NumSest to values that are not powers of two.
 - Improved PCI error interrupts processing.
 - Added a fix so a response is issued before target mode exchanges are aborted.
 - Task management handling has been improved.
 - Added support for port level Execution Throttle with a default value of 255 (disabled).

3. Known Issues/Advisements

- No known advisements.

4. Affected Products

Product Name	SKU
ThunderLink FC 1082 Desklink Device	TLFC-1082-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com