



ThunderLink™ FC 2162 Release v1.05 - Mac OS® X

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 2162 Thunderbolt 2 to 16Gb Fibre Channel Desklink Device, version 1.05, which was released on 10/30/14. This information pertains to the Mac OS X platform for Intel® based systems.

2. Changes

- **Version 1.05 (Released 10/30/14)**
 - **New Features, Enhancements and Changes**
 - Addition of operating system Mac OS X 10.10
 - Corrected an issue where a cable pull could result in I/O failure in MultiPath Director instead of failing over to an alternate path.
 - Addressed resource and performance issues concerning the number of logins being generated by NPIV ports.
 - Addressed a firmware issue causing an error when two or more NPIV ports are querying a switch.
 - Changed the default setting for the LoginToTargetsOnly HW parameter to DISABLED.
 - Addressed an issue where firmware is unable to sustain a chip reset while I/O is in progress.
- **Version 1.00 (Released 09/02/14)**
 - **New Features, Enhancements and Changes**
- **Version 1.00 (Released 06/19/14)**
 - **New Features, Enhancements and Changes**
 - Initial release of Mac OS X driver for the ThunderLink FC 2162 Desklink Device.
 - **Supported OS**
 - Mac OS X 10.8
 - Mac OS X 10.9

3. Known Issues/Advisements

- No known advisements.

4. Affected Products

Product Name	SKU
ThunderLink FC 2162 Desklink Device	TLFC-2162-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com