



ATTO Technology, Inc.

Product Release Notes

ThunderLink Fibre Channel 2082 and 2162 Multipath Director Release V1.07MP – Mac OS® X

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink Fibre Channel 2082 and 2162 Desklink Devices version 1.07MP that was released on 01/27/2015. This information pertains to Mac OS X. **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.

2. Changes

- **Version 1.07MP (Released 01/27/2015)**
 - **New Features/Enhancement**
 - Improved I/O response underrun processing
 - Corrected a resource leak error

- **Version 1.05MP (Released 10/30/2014)**
 - **New Features/Enhancement**
 - Support for Mac OS X 10.10
 - Added support for Quantum StorNext QX series storage.
 - Active/non-optimized paths are activated for I/O in the same manner as standby paths by default.

- **Version 1.00MP**
 - **New Features/Enhancements**
 - Initial release of Mac drivers for the ThunderLink FC 2082/2162.
 - **Supported OS**
 - Mac OS X 10.6.8
 - Mac OS X 10.7
 - Mac OS X 10.8
 - Mac OS X 10.9

3. Known Issues/Advisements

- None

4. Affected Products

Product Name	SKU
ThunderLink FC 2082	TLFC-2082-D00/DE0
ThunderLink FC 2162	TLFC-2162-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com