



## ThunderLink™ NT 2102 Release v1.12 - Mac OS® X

### 1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink NT 2102 Thunderbolt 2 to 10GBASE-T Ethernet (RJ45 copper) Desklink Device, version 1.12, which was released on 07/11/14. This information pertains to the Mac OS X platform for Intel® based systems.

### 2. Changes

- **Version 1.12 (Released 07/11/14)**
  - **New Features, Enhancements and Changes**
    - Added support for Receive Side Coalescing.
    - Resolved a leak in the I/O request pool when the driver is unloaded and reloaded within 60 seconds.
- **Version 1.11 (Released 05/09/14)**
  - **New Features, Enhancements and Changes**
    - Initial release for the ThunderLink NT 2102 Desklink Device.

### 3. Known Issues/Advisements

- No known advisements.

### 4. Affected Products

Product Name	SKU
ThunderLink NS 1101 Desklink Device	TLNS-1101-D00/DE0
ThunderLink NT 1102 Desklink Device	TLNT-1102-D00/DE0
ThunderLink NS 2102 Desklink Device	TLNS-2102-D00/DE0
ThunderLink NT 2102 Desklink Device	TLNT-2102-D00/DE0

### 5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)