



ThunderStream® SC 4808 Release v1.35 - Mac OS®

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderStream SC 4808 RAID Storage Controller Thunderbolt Device, version 1.35, which was released on 09/20/16. This information pertains to OS X® 10.9 and later as well as macOS Sierra platform for Intel® based systems.

2. Changes

- **Version 1.35 (Released 09/20/16)**
 - **Note:** It is recommended that firmware dated 01/29/16 be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Added support for macOS Sierra
 - Added rotational logging support to limit the size of the event log. Now allowing for up to five 50 MB log files will be created
 - Improvements to stability when running heavy I/O

- **Version 1.30 (Released 02/02/16)**
 - **Note:** It is recommended that firmware dated 01/29/16 be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Resolved error where events that happened prior to the driver loading may be lost.
 - Enhancement to detect when the firmware has been reset before the driver has loaded and attempt to save the core dump and recover the firmware.
 - Added support for extended atreset functionality.
 - The fully qualified driver version is displayed in the installer.
 - Additional recovery for firmware core dump when the heartbeat fails on firmware.

- **Version 1.25 (Released 09/10/15)**
 - **Note:** It is recommended that firmware dated 09/03/15 be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Improved processing of the max transfer size values set by the Config Tool
 - The event logging service has been improved to use less system resources
 - Updated the installer to function in Mac OS X 10.11.
 - Added support for extended atreset functionality.

- **Version 1.20 (Released 02/23/15)**
 - **Note:** It is recommended that firmware dated 02/03/15 be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Initial release for the ThunderStream 4808D device.

3. Known Issues/Advisements

- Note: Please contact ATTO Technical Support if you need additional information or assistance with these configuration suggestions.

4. Affected Products

Product Name	SKU
ThunderStream SC 4808D Device	TSSC-4808-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com