



## ThunderStream™ SC 4808 Release v1.20 - Windows®

### 1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderStream SC 4808 RAID Storage Controller Desklink Device, version 1.20, which was released on 02/02/16. This information pertains to Microsoft Windows Operating System.

### 2. Changes

- **Version 1.20 (Released 02/02/16)**
  - **Note:** It is recommended that firmware dated 01/29/16 be utilized with this driver release.
  - **New Features, Enhancements and Changes**
    - Enhancement to detect when the firmware has been reset before the driver has loaded and attempt to save the core dump and recover the firmware.
    - Event log messages for firmware faults have been updated to indicate the specific condition that occurred.
- **Version 1.15 (Released 02/23/15)**
  - **Note:** It is recommended that firmware dated 02/03/15 be utilized with this driver release.
  - **New Features, Enhancements and Changes**
    - Initial release for the ThunderStream 4808 Desklink device.

### 3. Known Issues/Advisements

- Note: Please contact ATTO Technical Support if you need additional information or assistance with these configuration suggestions.

### 4. Affected Products

Product Name	SKU
ThunderStream SC 4808D Desklink Device	TSSC-4808-D00/DE0

### 5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)