



ATTO Technology, Inc.

## Product Release Notes

# Celerity 16Gb Fibre Channel Multipath Director™ Release v1.03MP – Mac OS® X

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the Celerity 16Gb Fibre Channel adapter product v1.03MP that was released on 6/27/2013. This information pertains to the Mac OS X 10.6, 10.7 and 10.8.

### 2. Changes

---

- **Version 1.03MP (Released 6/27/2013)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - **New Features**
    - Corrected an issue where I/O could be stopped to a device after a link goes down.
- **Version 1.02MP (Released 4/10/2013)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - **New Features**
    - Added ‘—m’ option with the same functionality as the standard driver.
    - Corrected out of resource processing when the mapped controller and destination controller for an I/O are different.
- **Version 1.01MP (Released 1/15/2013)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - **New Features**
    - Changed the default Execution Throttle to 255 (disabled).
    - Implemented interrupt coalescing.
    - Fixed event Log messages so lost frames report with the correct error code.
    - Corrected an issue that could result in devices not being found after waking from sleep.
    - Corrected target identifier determination for certain arrays.
    - Disabled multipathing for certain arrays that do not report proper device identification.
- **Version 1.00MP (Released 11/08/2012)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - **New Features**
    - Initial release of Mac OS X multipathing drivers for the Celerity 16Gb FC adapters.
  - **Supported OS**
    - Mac OS X 10.6
    - Mac OS X 10.7
    - Mac OS X 10.8

### 3. Known Issues/Advisements

---

- Multiple direct connections to a Xyratex drive array do not work.
- Celerity quad-channel (FC-164E) is not supported on Mac operating system.

#### 4. Affected Products

---

| Product Name     | SKU           |
|------------------|---------------|
| Celerity FC 161E | CTFC-161E-000 |
| Celerity FC 162E | CTFC-162E-000 |

#### Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)