



ATTO Technology, Inc.

Product Release Notes

Celerity 8Gb Fibre Channel Multipath Director Release V2.16MP – Linux®

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the Celerity 8Gb Fibre Channel adapter product v2.16MP that was released on April 16th, 2018. This information pertains to the following operating systems: Red Hat Enterprise Linux 6, 7; CentOS 6, 7; SUSE Linux Enterprise Server 11sp4, 12; OpenSUSE Linux 13.2, 42.1; Ubuntu 16.04 LTS.

2. Changes

- **Version 2.16MP (Released 4/16/2018)**
 - **Note:** It is recommended that latest firmware available on ATTO website be used with this driver release.
 - Added support for a new flash bundle format that supports smaller download portions compatible with the maximum transfer size for the driver
 - Addressed timer API compatibility in kernel 4.15 and later
 - Improved interoperability with SLES 11.4 and SLES 12.3
 - Fixed support for atfcvnr to change the node WWN
 - Improved support with SCST target mode
 - Updated default module parameters for improved performance
 - Additional support for Promise VTrak E630f and the DotHill DH3000
 - Improvements to displaying which offline devices are being presented to the OS (and displayed in ConfigTool).
 - Note: As a result of this change, previously saved configurations may need to be deleted and resaved to display correctly after reboot
- **Version 2.15.0MP (Released 12/18/2017)**
 - **Note:** It is recommended that latest firmware available on ATTO website be used with this driver release.
 - **New Features/Enhancements**
 - Full Inquiry data is now reported for multipathed devices
 - Added ability to uninstall included CLI Tools and added additional CLI tools: atdevinfo, atfcinfo, and atlocate to the release package.
 - Enabled atto_log_mask based logging
 - Resolved compilation error on 4.12 and later kernels
 - Removed driver module parameters that have NVRAM equivalents
- **Version 2.10MP (Released 05/03/2017)**
 - **Note:** It is recommended that latest firmware available on ATTO website be used with this driver release.
 - **New Features/Enhancements**
 - Added support for Ubuntu 16.04 LTS
 - Added support for the Seagate 5825 storage array
 - Updated builds for kernel 4.3, and later

- **Version 2.05MP (Released 12/20/2016)**
 - **Note:** It is recommended that latest firmware available on ATTO website be used with this driver release.
 - **New Features/Enhancements**
 - Added support for Dot Hill 6424 and 6844 storage.
 - Enabled MSI-X interrupt support
 - Modified driver to automatically unload the *attocfg* driver when switching between the MP and standard drivers
 - Reworked *ioctl* code to directly access user memory instead of double-buffering
 - Resolved issue with 32-bit driver builds for 4.x kernels
 - Modified driver to ensure INQUIRY data is correctly reported to the operating system

- **Version 2.01MP (Released 09/01/2016)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Fixed an issue that could cause excessive completion times for failover or discovery
 - Enabled LU-based MP for Quantum QXS storage

- **Version 2.00MP (Released 06/30/2016)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Now supports LU-based multipathing.
 - Added support for configuring an alias.
 - Fixed an issue with potential hangs by offlining targets before removing them.

- **Version 1.96MP (Released 05/09/2016)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Corrected an issue with Reinstatement Recovery Qualifier not being properly rejected when sent by a target to the adapter.

- **Version 1.95MP (Released 01/21/2016)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Resolved a connection issue with previous versions of EMC storage
 - Updates to CLI tools and readme

- **Version 1.90MP (Released 8/06/2015)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Implemented T10-PI management improvements
 - Addressed a kernel panic that occurs during boot

- **Version 1.85MP (Released 3/19/2015)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Added support for Fedora 21
 - Added support for SUSE Linux Enterprise Server 12
 - Resolved an RSCN discovery issue.
 - Now support the ability to map LUNs to LUNs and targets to targets
 - ALUA devices are now allowed to change the path mode from disabled to the default
 - Active/non-optimized paths are activated in the same manner as standby path by default.

- Corrected identifier determination for some storage. As a result, previously saved configuration will no longer be in effect for some arrays. The configuration must be resaved after upgrading.
 - Resolved a memory leak issue.
 - Addressed an I/O failure during controller reset.
- **Version 1.81MP (Released 1/15/2015)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Added support DotHill arrays
 - Added support for Quantum StorNext arrays
- **Version 1.80MP (Released 10/30/2014)**
 - **New Features/Enhancements**
 - Added support for RHEL 7
 - Addressed a model description error
- **Version 1.75MP (Released 9/25/2014)**
 - **New Features/Enhancements**
 - Added new display information for atmpinfo
 - Added support for atreset
 - Added support for device display in atinfo
 - Addressed an issue where IO to a LUN could be stalled
 - Set default so that active/non-optimized paths are activated for IO in the same manner as standby paths
 - Addressed a failover issue when the preferred path is removed
 - Reduced the time it takes to discovery newly added LUNs using the rescan paths button.
 - Resolved an issues where MultiPath Director was no longer available after reboot
- **Version 1.50MP (Released 2/06/2014)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Corrected an issue with path discovery for paths that are deactivated immediately after being found.
 - Addressed an issue with deactivating paths that are disabled due to I/O errors.
 - Fixed an issue where discovery or failover of a path could be delayed by a transitioning asymmetric access state for a port group that did not apply to the path.
 - Resolved an issue where simultaneously reporting device changes on multiple HBA channels could result in the multipathed devices from being activated
 - Addressed an issue where path selection could prematurely fail an I/O when the last remaining path failed simultaneously
 - Corrected an issue where path rediscovery would not activate the path after the link down timeout previously expired
 - Paths that have a scan pending are considered retrying so I/O is suspended when no paths are active.
 - Feature added to allow path activations and deactivations during the link down timeout period to coordinate with other device events to prevent invalid path states.
 - Resolved a system hang on RedHat 5.9.
 - Fixed a kernel panic on StorNext MDC during controller firmware update test.
 - Addressed an issue where LUNs are not presented properly on SUSE 11 SP3.
 - Fixed multiple problems when handling aborted commands.
 - Corrected soft lockups reported during MP scans.
 - Enhanced performance on systems with >4GB RAM.

- **Version 1.41MP (Released 6/27/2013)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Corrected Config Tool reporting error where the same LUN shows multiple times with MultiPath Director.
- **Version 1.40MP (Released 12/21/2012)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - **New Features/Enhancements**
 - Resolved issue where all paths were not reported properly on HP MSA P2000.
- **Version 1.39MP (Released 12/04/2012)**
 - **New Features/Enhancements**
 - Change made to obtain the correct target identifier for some arrays.
 - Feature added to disable multi-pathing for certain arrays.
- **Version 1.38MP (Released 10/24/2012)**
 - **New Features/Enhancements**
 - Inquire failure will not cause path removal.
 - Resolved panic during sysreboot test.
- **Version 1.37MP (Released 09/17/2012)**
 - **New Features/Enhancements**
 - Support for NetApp firmware version 7.83
 - Support failover mode in saved configurations.
 - Resolved issue where LUNs failover after reboot regardless of 'mp disable fallback' setting.
 - Added support for MP check/block states.
 - Added feature to restart LUN scan or target scan based on sense data.
 - Added ability to disable fallback.
- **Version 1.36MP (Released 08/21/2012)**
 - **New Features/Enhancements**
 - Resolved panic in RH 6.1 for specific SCSI command.
- **Version 1.35MP (Released 08/08/2012)**
 - **New Features/Enhancements**
 - Resolved issue where paths are not updated unless data is being passed.
 - Resolved IO failure in Linux during controller failover.
 - Resolved panic when a controller is rebooted.
 - Full controller LUN trespass support.
 - Stornext volume can now be accessed if controlling MDC fails.
- **Version 1.34MP (Released 05/04/2012)**
 - **New Features/Enhancements**
 - Addressed an incompatibility with certain Promise devices running in Point-to-Point mode.
 - Corrected an issue in which setting a saved multipathing configuration could fail when the device is not configurable.
- **Version 1.33MP (Released 02/02/2012)**
 - **New Features/Enhancements**
 - Made additional improvements to bus reset handling.
- **Version 1.32MP (Released 07/20/2011)**
 - **New Features/Enhancements**

- Resolved a panic which occurred when removing the ATTO driver while drives are being spun up.
 - New system logging macros are being used.
 - Contains fix for dropped PLOGIs or PRLIs.
- **Version 1.30MP (Released 03/30/2011)**
 - **New Features/Enhancements**
 - Added support for the Access LUN in IBM DSxxxx arrays.
 - Added support for EMC CLARiiON AX series storage.
 - Added support for HP MSA series storage.
 - Target based identifiers in Inquiry VPD page 0x83 are given priority over LUN based identifiers in determining how to multipath devices.
 - Devices that report an unknown device type in Inquiry data are ignored.
 - Resolved panic in RH5.4.
- **Version 1.24MP (Released 12/07/2010)**
 - **New Features/Enhancements**
 - Feature improvement related to task management.
 - Added atmpininfo binary to tarball for MP builds.
 - Improved the adapter recovery mechanism after a reset.
 - Added support for Red Hat Enterprise Linux 6.
- **Version 1.23MP (Released 07/30/2010)**
 - **New Features/Enhancements**
 - Support added for T10-DIF
 - The command line switch T10dif has the default setting as 0 (disabled). To enable, change setting to one (1).
 - When enabled, the driver will detect if a disk drive is formatted for T10-DIF. Upon detection of T10-DIF, the driver will automatically generate the DIF field on the writes, and check it on the reads.
 - This feature currently does not provide a mechanism to format the drive.
- **Version 1.21MP (Released 03/05/2010)**
 - **New Features/Enhancements**
 - Resolved IO failure during firmware up/down grade testing.
- **Version 1.20MP (Released 03/05/2010)**
 - **New Features/Enhancements**
 - Initial release of Linux MP Director code based on OS X driver.

Known Issues/Advisements

- Fibre Channel performance can be reduced significantly if the 8Gb Celerity HBA is placed in a Supermicro main board that uses the Intel 5520 (Tylersburg) chipset. The workaround is to disable Active State Power Management (ASPM) within the Linux Operating System (not the BIOS as Linux does not honor ASPM BIOS settings). Contact ATTO Tech Support for more information.
- After creating an entry in /etc/fstab for a LUN with file system check enabled, a subsequent reboot may cause the file system check to fail if the LUN is not ready. The work around is to use the "_netdev" option in the /etc/fstab entry. For example:
 - /etc/fstab entry with _netdev option:

```
UUID=xxxxxxxx-xxxx-xxxx-xxxx-xxxxxxxxxxxxx/fs0 ext4 defaults,_netdev 02
```
- In Linux environments, set "intel_immou=off" in the kernel when using Multipath Director (MPD) drivers. It is also recommended that VT-d be disabled in the system BIOS (if available)

3. Affected Products

Product Name	SKU
Celerity FC 81EN	CTFC-81EN-000

Celerity FC 82EN	CTFC-82EN-000
Celerity FC 84EN	CTFC-84EN-000

4. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit <https://www.attotech.com/support/> for hours of operation.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com