



ATTO Technology, Inc.

## Product Release Notes

# ThunderLink Fibre Channel 3162/3322 Multipath Director Release V2.15MP – Windows

### 1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink Fibre Channel 3162/3322 adapter product v2.15MP that was released on 12/18/17. This information pertains to Windows Operating systems. **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.

### 2. Changes

- **Version 2.15MP (Released 12/18/2017)**
  - **New Features & Enhancements**
    - Added HP MSA 2050 storage array support.
    - Full Inquiry data is now reported for multipathed devices.
- **Version 2.10MP (05/03/17)**
  - **New Features/Enhancements**
    - Added support for the Seagate 5825 storage array
  - **Supported OS**
    - Windows 10, 8.1, 8, 7.
- **Version 2.05MP (03/28/17)**
  - **New Features/Enhancements**
    - Initial release of the ThunderLink 3162 and 3322.
  - **Supported OS**
    - Windows 10, 8.1, 8, 7.

### 3. Known Issues/Advisements

- Currently, no known issues.

### 4. Affected Products

Product Name	SKU
ThunderLink FC 3162 device	TLFC-3162-D00
ThunderLink FC 3322 device	TLFC-3322-D00

### 5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit <https://www.attotech.com/support/> for hours of operation.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)