



## ThunderLink™ FC 3162 and 3322 Release v1.40 – Windows®

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 3162 and 3322 Thunderbolt Devices, version 1.40, which was released on 05/03/17. This information pertains to Microsoft Windows Operating System including Windows 7, 8, 8.1 and 10.

### 2. Changes

---

- **Version 1.40 (Released 05/03/17)**
  - **New Features, Enhancements and Changes**
    - Added support for atinfo to display the SFP serial number
- **Version 1.35 (Released 03/28/17)**
  - **New Features, Enhancements and Changes**
    - Initial release of the ThunderLink 3162 and 3322

### 3. Known Issues/Advisements

---

- Currently, no known issues.

### 4. Affected Products

---

Product Name	SKU
ThunderLink FC 3162	TLFC-3162-D00/DE0
ThunderLink FC 3322	TLFC-3322-D00/DE0

### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, Please visit <https://www.attotech.com/support/> for hours of operation.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)