



ATTO Technology, Inc.

## Product Release Notes

# ThunderLink® Fibre Channel 3322 and 3162 Multipath Director™ Release v2.16 – macOS®

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink Fibre Channel 3322 and 3162 Thunderbolt Devices version 2.16MP that was released on April 21, 2017. This information pertains to macOS Sierra and later.

### 2. Changes

---

- **Version 2.16MP (Released 4/21/2017)**
  - **Note:** It is recommended that the latest flash bundle available on ATTO website be utilized with this driver release.
  - **New Features/Enhancements**
    - Initial release of the ThunderLink Fibre Channel 3322 and 3162

### 3. Affected Products

---

Product Name	SKU
ThunderLink FC 3322	TLFC-3322-D00/DE0
ThunderLink FC 3162	TLFC-3162-D00/DE0

### 4. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)