



ATTO Technology, Inc.

Product Release Notes

ThunderLink™ NS 2101/2102/1101 and NT 2102 Release Windows v18.7

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink NS 2101/2102/1101 and NT 2102/1102 Thunderbolt 2 Desklink Devices, version 18.7, which was released on 06/22/15. This information pertains to the Windows7, 8.1 and later platform for Intel® based systems.

2. Changes

- **Version 18.7** (06/22/15)
 - Initial Release of Windows Drivers for ATTO Desklink Devices

3. Known Issues/Advisements

Thunderbolt hot unplug with latest x86 Intel driver (ProWin32.exe v18.7) can prevent subsequent Thunderbolt discovery

4. Affected Products

Product Name	SKU
ThunderLink NS 2102 Desklink Device	TLNS-2102-D00/DE0
ThunderLink NS 2102 Desklink Device (Low Profile)	TLNS-2102-D01/DE1
ThunderLink NS 2102 Desklink Device	TLNS-2101-D00/DE0
ThunderLink NT 2102 Desklink Device	TLNT-2102-D00/DE0
ThunderLink NS 1101 Desklink Device	TLNS-1101-D00/DE0
ThunderLink NT 1102 Desklink Device	TLNT-1102-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit attotech.com/support for technical support hours.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com