



Product Release Notes

ThunderLink™ SH 2068 Flash Bundle Version 150203

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink SAS Host 2068 Desklink Device flash bundle package which was released on 02/23/15. This information pertains to the flash bundles and BIOS utility associated with the ThunderLink SAS Host products.

2. New Features, Enhancements and Changes

- **Version 150203 (Released 02/23/15)**
 - **New Features, Enhancements and Changes**
 - Initial release of firmware (1.00) for the ThunderLink SH 2068.

3. Known Issues/Advisements

- Note:** Please contact ATTO Technical Support if you need additional information or assistance with these configuration suggestions.
- There is an interoperability issue with Toshiba MK2002TSKB 3Gbps SATA drives. A workaround for the issue is to disable NCQ.

4. Affected Products

Product Name	SKU
ThunderLink SH 2068 Desklink Device	TLSH-2068-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com