



## ThunderLink® Fibre Channel Release v2.11 - VMware

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to ThunderLink™ Fibre Channel Release v2.11 – VMware that was released on 08/24/2017. This information pertains to VMware ESXi 5.5 and later.

### 2. Changes

---

- **Version 2.11 (Released 08/24/2017)**
  - **Note:** It is recommended that latest firmware, available on the ATTO website for ThunderLink Fibre Channel products, be utilized with this driver release.
  - **New Features, Enhancements and Changes**
    - Initial release of VMware Ready driver for VMware ESXi.

### 3. Known Issues/Advisements

---

- This driver does not respond to disconnects and reconnect of ThunderLink devices. To maintain functionality the driver shall be connected at boot time and will not be disconnected while the system is running.
- This driver does not support daisy chaining of Thunderbolt devices. The ATTO ThunderLink device should be the only Thunderbolt device connected.
- ATTO CLI Tools are not available with the VMware ThunderLink driver.

### 4. Affected Products

---

Product Name	SKU
ThunderLink FC 2082	TLFC-2082-D00/DE0
ThunderLink FC 2162	TLFC-2162-D00/DE0

### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)