

ATTO FibreBridge 2390/2400 Interoperability Matrix

| | 2390C/R/D | 2400C/R/D | |
|------------------------------------------|--------------------------------------|-----------|---|
| Operating System | Apple Tiger OS 10.4.X | X | X |
| | Apple Panther OS 10.3.X | X | X |
| | Linux: RedHat | X | X |
| | Sun Solaris 10 | X | X |
| | Windows XP, Server 2003, 2000, Vista | X | X |
| Fibre Channel HBA's | ATTO Celerity | X | X |
| | Emulex LP11002 | X | X |
| | Emulex LPe11002 | X | X |
| | LSI 7204XP-LC | X | X |
| | QLogic 2462 | X | X |
| | QLogic 2362 | X | X |
| Fibre Channel Switches | Brocade Silkworm 200E | X | X |
| | Brocade Silkworm 4100 | X | X |
| | Cisco MDS9216 | X | X |
| | QLogic SANbox 3100 | X | X |
| | QLogic SANbox 5602 | X | X |
| Removable Tape / MO Storage | ADIC Scalar 24 | X | X |
| | ADIC Scalar 100 | X | X |
| | Exabyte VXA-2 Packetloader | X | X |
| | HP LTO1 | X | X |
| | HP LTO2 | X | X |
| | HP LTO3 | X | X |
| | IBM LTO1 | X | X |
| | IBM LTO2 | X | X |
| | IBM LTO3 | X | X |
| | Overland NEO 2000 | X | X |
| | Plasmon G-Series | X | X |
| | Qualstar RLS Series | X | X |
| | Qualstar TLS Series | X | X |
| | Quantum M1500 | X | X |
| | Quantum M2500 | X | X |
| | Quantum Superloader | X | X |
| | Quantum DLT 8000 | X | X |
| | Quantum SDLT 320 | X | X |
| | Quantum SDLT 600 | X | X |
| | Sony AIT-3 | X | X |
| | Sony AIT-4 | X | X |
| | Sony SAIT-1 | X | X |
| Sony SM-20 | X | X | |
| Sony LIB-81 | X | X | |
| Sony LIB-162 | X | X | |
| Independent Software Applications | BakBone Netvault | X | X |
| | CA ArcServe | X | X |
| | Commvault Galaxy | X | X |
| | EMC/Dantz Retrospect | X | X |
| | Legato Networker | X | X |
| | Sanbolic LaScala/MelioFS | X | X |
| | Veritas BackupExec | X | X |
| | Veritas NetBackup | X | X |
| | Windows 2003 Native Backup | X | X |

Disclaimer: The ATTO Interoperability Matrix is a general guideline that is not specific to firmware, version, revision, specification level or test configuration of ATTO or third-party products. ATTO Technology tests products on an ongoing basis and new equipment is constantly being added. The Interoperability Matrix may not reflect the most current information. If a specific product is not shown, please contact ATTO Technical Services at 800-858-9598 for additional information. Inclusion of any product on this list does not guarantee compatibility. Customer-specific configurations may influence compatibility. Please check the ATTO Technology website at www.attotech.com for additional details.