



ATTO Technology, Inc.

# Product Release Notes

## Celerity Fibre Channel Release v2.62 - Windows

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the Celerity Fibre Channel adapter product v2.62 that was released on 2/29/2008. This information pertains to the Windows XP, Vista, Server 2003 and 2008 OS.

### 2. Changes

---

- **Version 2.62 (Released 2/29/2008)**
  - **Note:** It is recommended that firmware dated 8/26/08 be utilized with this driver release.
  - The following apply to changes made from v2.61 to v2.62
  - **New Features**
    - Drivers verified for Windows Server 2008
    - Driver support for Microsoft WHQL certification
    - Updated Attomtn.inf for Windows Server 2008 certification
    - Added a custom icon and the ability to automatically run Setup.exe to the self-extracting EXEs
    - Fixed a locking issue that caused the LUN Masking Utility to hang when saving certain settings
    - Now provide MiniPort driver support for Windows XP x64

### 3. Known Issues/Advisements

---

- None

#### 4. Affected Products

---

Product Name	SKU
Celerity FC 44ES	CTFC-44ES-000
Celerity FC 42ES	CTFC-42ES-000
Celerity FC 41ES	CTFC-41ES-000
Celerity FC 41EL	CTFC-41EL-000
Celerity FC 42XS	CTFC-42XS-000
Celerity FC 41XS	CTFC-41XS-000

#### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)