



Celerity 16Gb Gen 5 and 16Gb/32Gb Gen 6 Fibre Channel Release v1.02 - illumos

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the Celerity 16Gb Gen 5 and 16Gb/32Gb Gen 6 Fibre Channel HBA product line driver v1.02 that was released on November 5, 2018. This information pertains to the following illumos operating system distributions: OpenIndiana, NextenaStor 5, and NexentaStor 4.

2. Changes

- **Version 1.02 (Released 11/05/2018)**
 - **Note:** It is recommended that firmware dated 11/05/2018 be used with this driver release.
 - **New Features, Enhancements and Changes**
 - Increased the number of I/O resources to improve performance.
 - Fixed support for atfcnvr to change the node WWN
 - Add several performance optimizations for potential performance improvements based on workload.
 - Improved target mode performance
 - Added support for the built-in fcinfo / fcdm illumos tools
 - Added CLI tool installation location to the README
- **Version 1.01 (Released 08/22/2018)**
 - **Note:** It is recommended that firmware dated 08/08/2018 be used with this driver release.
 - **New Features, Enhancements and Changes**
 - Initial release of illumos driver for Celerity HBAs

3. Known Advisements

- None

4. Affected Products

Product Name
Celerity FC-161E
Celerity FC-162E
Celerity FC-161P
Celerity FC-162P
Celerity FC-164P
Celerity FC-321E
Celerity FC-322E
Celerity FC-324E

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@atto.com