



ATTO Technology, Inc.

# Product Release Notes

## Celerity 16Gb Fibre Channel Release v1.01 – Mac OS X

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the Celerity 16Gb Fibre Channel adapter product v1.02 that was released on 1/15/2013. This information pertains to the Mac OS X 10.6, 10.7 and 10.8.

### 2. Changes

---

- **Version 1.01 (Released 1/15/2013)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - The following apply to driver v1.01
  - **New Features**
    - Changed the default Execution Throttle to 255 (disabled)
    - Implemented interrupt coalescing
    - Fixed event Log messages so lost frames report with the correct error code
    - Corrected an issue that could result in devices not being found after waking from sleep
  
- **Version 1.00 (Released 11/08/2012)**
  - **Note:** It is recommended that firmware dated 11/08/2012 be utilized with this driver release.
  - The following apply to driver v1.00
  - **New Features**
    - Initial release of Mac drivers for the Celerity 16Gb FC adapters
  - **Supported OS**
    - Mac OS X 10.6
    - Mac OS X 10.7
    - Mac OS X 10.8

### 3. Known Issues/Advisements

---

- Multiple direct connections to a Xyratex drive array do not work.
- Celerity quad-channel (FC-164E) is not support on Mac operating system.

### 4. Affected Products

---

Product Name	SKU
Celerity FC 161E	CTFC-161E-000
Celerity FC 162E	CTFC-162E-000

## 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)