



Celerity Fibre Channel Release v2.70 - Linux

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the Celerity Fibre Channel adapter product v2.70 that was released on 2/2/2012. This information pertains to the Linux OS.

2. Changes

- **Version 2.70 (Released 2/2/2012)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - The following apply to changes made from v2.66 to v2.70
 - Changes to minimize risk of errors when loading driver in Red Hat 6

- **Version 2.66 (Released 12/13/2010)**
 - **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.
 - The following apply to changes made from v2.64 to v2.66
 - Added support for Red Hat Enterprise Linux 6
 - Improved interoperability with latest versions of Linux distribution

- **Version 2.64 (Released 12/3/2008)**
 - **Note:** It is recommended that firmware dated 091119 be utilized with this driver release.
 - The following apply to changes made from v2.63 to v2.64
 - **Incident Resolutions/Bug Fixes/Changes**
 - Improved initiator task management
 - Miscellaneous compilation fixes
 - Fixed a bug in Linux-Rescan-Host-Routine that could lead to invalid outstanding references to the driver. This would prevent the driver from being unloaded
 - OEM Specific 42RO

- **Version 2.62 (Released 6/9/2008)**
 - **Note:** It is recommended that firmware dated 11/13/07 be utilized with this driver release.
 - The following apply to changes made from v2.61 to v2.62
 - **Incident Resolutions/Bug Fixes/Changes**
 - Support added for Linux Kernel 2.6.25
 - Addressed hardware check while loading Linux
 - Fixed an issue that would only show 6 of 8 ports if two (2) 44ES Celerity host adapters were installed in the same machine.

- **Version 2.61 (Released 2/29/2008)**

- **Note:** It is recommended that firmware dated 11/13/07 be utilized with this driver release.
- The following apply to changes made from v2.60 to v2.61
- **New Features**
 - Full driver support for the 41EL Host adapter

3. Known Issues/Advisements

- None

4. Affected Products

Product Name	SKU
Celerity FC 44ES	CTFC-44ES-000
Celerity FC 42ES	CTFC-42ES-000
Celerity FC 41ES	CTFC-41ES-000
Celerity FC 41EL	CTFC-41EL-000
Celerity FC 42XS	CTFC-42XS-000
Celerity FC 41XS	CTFC-41XS-000

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com