



Celerity Fibre Channel Release v1.10 - VMware

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the Celerity Fibre Channel adapter product v1.10 that was released on 9/15/2009. This information pertains to the VMware ESX Server v3.5 OS update 4.

2. Changes

- **Version 1.10 (Released 9/15/2009)**
 - **Note:** It is recommended that firmware dated 091119 be utilized with this driver release.
 - *Initial release of VMware ESX 3.5 driver for the Celerity 8Gb FC adapters.*
 - **New Features**
 - Documented support for VMware ESX Server v3.5
 - Incorporated TSDK6 & HW layer. This provides a more stable base for the VMware driver and includes a fix for VMware locking up when a target reset is issued.
 - Built using version 3.5.1 of DDK.
 - Race condition during reset handling causes double completion and kernel panic (purple screen)

3. Known Issues/Advisements

- ADT fails in VMware on Windows Server 2003 with 15 drives. This problem is clearly caused by the LSI Logic SCSI controller/driver that is installed in the 2003 Virtual Machine. The problem does not occur with other operating systems installed in Virtual Machines, nor does it occur with the BusLogic SCSI controller/driver in a Windows 2003 Virtual Machine.

4. Affected Products

Product Name	SKU
Celerity FC 84EN	CTFC-84EN-000
Celerity FC 82EN	CTFC-82EN-000
Celerity FC 81EN	CTFC-81EN-000

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com