



Celerity Fibre Channel Release v1.36 - VMware

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the 8Gb Celerity Fibre Channel adapter product v1.36 that was released on 07/08/2014. This information pertains to the VMware ESXi Server v5.x OS.

2. Changes

- **Version 1.36 (Released 07/08/2014)**
 - **Note:** It is recommended that latest firmware, available on the ATTO website for 8Gb Celerity Fibre Channel Host Bus Adapters, be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Added support for VMware ESXi 5.5
 - IO Device Management (IODM) logging now supported. IODM provides new commands to help administrators troubleshoot issues with I/O devices and fabrics.
- **Version 1.33 (Released 10/31/2011)**
 - **Note:** It is recommended that latest firmware, available on the ATTO website for 8Gb Celerity Fibre Channel Host Bus Adapters, be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Added support for NPIV
 - Improved functionality in NPIV vMotion
 - Improved handling of Windows 2k3 r2 x64 (or better) installation in a VM
- **Version 1.32 (Released 10/10/2011)**
 - **Note:** It is recommended that latest firmware, available on the ATTO website for 8Gb Celerity Fibre Channel Host Bus Adapters, be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Adjustment was made to the Vendor string in the driver bundle.
- **Version 1.31 (Released 8/22/2011)**
 - **Note:** It is recommended that latest firmware, available on the ATTO website for 8Gb Celerity Fibre Channel Host Bus Adapters, be utilized with this driver release.
 - *Initial release of VMware ESXi 5.x driver for the Celerity 8Gb FC adapters.*
 - **New Features, Enhancements and Changes**
 - Documented support for VMware ESXi Server v5.x.
 - Includes support for N_Port ID Virtualization (NPIV).

3. Known Issues/Advisements

- *There are currently no known issues or advisements*

4. Affected Products

| Product Name | SKU |
|------------------|---------------|
| Celerity FC 84EN | CTFC-84EN-000 |
| Celerity FC 82EN | CTFC-82EN-000 |
| Celerity FC 81EN | CTFC-81EN-000 |

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com