



ATTO Technology, Inc.

Product Release Notes

ExpressSAS Host Adapter 12Gb Flash Bundle v140730

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ExpressSAS 12Gb Host Adapter flash bundle package, version 140730, which was released on August 1, 2014. This information pertains to the flash bundles and EFI utility associated with the ExpressSAS 12Gb Host Adapter products.

2. Changes

- **Version 140730/EFI v1.05 (Released 8/1/2014)**
 - **New Features, Enhancements and Changes**
 - Incorporated firmware 3.07.40.
 - Resolved an issue regarding correct interpretation of descriptor based sense data during the driver's device scan.
 - Increased the wait time for devices to become ready from 30 to 60 seconds.
- **Version 140423/EFI v1.00 (Released 5/2/2014)**
 - **New Features, Enhancements and Changes**
 - Initial release for the H1280, H1208, H12F0 and H120F.

3. Known Issues/Advisements

- A corrupted data frame transmitted by a device and recovered by Transport Layer Retries may be completed with an I/O error to the host application.

4. Affected Products

Product Name
ExpressSAS H1208
ExpressSAS H1280
ExpressSAS H12F0
ExpressSAS H120F

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com