



ExpressSAS Host Adapter 6 Gb Release v1.00 - VMware®

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ExpressSAS Host Adapter 6 GB products v1.00 that was released on 03/19/10. This information pertains to the VMware ESX Server 3.5 OS update 5.

2. Changes

- **Version 1.00 (Released 03/19/10)**
 - **Note:** It is recommended that firmware dated 07/27/09 be utilized with this driver release.
 - Maintenance release of VMware ESX 3.5 u5 driver for the ExpressSAS 6GB SAS adapters.
 - **New Features, Enhancements and Changes**
 - VMware re-build of drivers for ESX 3.5 U5 release.

3. Known Issues/Advisements

- VMware ESX Server 3.5 does not support SAS 2.0 devices. Therefore, the ExpressSAS H6xx product family will only be treated as a SAS 1.0 device by ESX Server.

4. Affected Products

Product Name	SKU
ExpressSAS H680 Host Adapter	ESAS-H680-000
ExpressSAS H608 Host Adapter	ESAS-H608-000
ExpressSAS H6F0 Host Adapter	ESAS-H6F0-000
ExpressSAS H60F Host Adapter	ESAS-H60F-000
ExpressSAS H644 Host Adapter	ESAS-H644-000

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com