



ATTO Technology, Inc.

Product Release Notes

ExpressSAS Host Adapter 6 Gb v1.00 – Linux

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ExpressSAS Host adapter products v1.00 that was released on 12/11/2008. This information pertains to Linux.

2. Known Issues/Advisements

- **Version 1.00 (Released 12/11/2008)**
 - **Note:** It is recommended that firmware dated 2008_12_05 be utilized with this driver release.
 - The following applies to release v1.00
 - **New Features**
 - Initial release of ExpressSAS H608 and H680

3. Known Issues/Advisements

- When performing writes (queue depth ≥ 2) with some SAS drives, the drives will periodically report a Check Condition for Overlapped Commands Attempted
- SAT exceptions: (SCSI-to-ATA Translation for SATA support). The following SCSI commands are not translated: FORMAT UNIT, REASSIGN BLOCKS, SECURITY PROTOCOL IN, and SECURITY PROTOCOL OUT

4. Affected Products

Product Name	SKU
ExpressSAS H680 Host Adapter	ESAS-H680-000
ExpressSAS H608 Host Adapter	ESAS-H608-000

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com