



ATTO Technology, Inc.

Product Release Notes

FastFrame™ 40GbE NIC v1.10 – RHEL/CentOS 7.3, SUSE Server 12 sp2

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the FastFrame 40GbE v1.10 Linux release, specifically RHEL 7.3, CentOS 7.3, and SUSE Linux Enterprise Server 12 sp 2.

2. Changes

- **Version 1.10 (Released 03/16/2017)**
 - **New Features, Enhancements, and Changes**
 - Added support for SLES12 service pack 2.
 - Added support for CentOS 7.3
 - Added support for RHEL 7.3
 - Added atflash2 utility to update firmware
- **Version 1.00 (Released 09/17/2015)**
 - **New Features, Enhancements and Changes**
 - Initial release for the FastFrame 40GbE NIC drivers for Linux

3. Known Issues/Advisements

- May not be compatible with Mellanox OFED. If OFED is installed, uninstalling the compat-rdma package may help
- Flash utility support upcoming
- Kernel panic may occur if SLES12 is configured to act as an NFS-over-RDMA server

4. Affected Products

Product Name	SKU
FastFrame 40GbE NICs	FFRM-NQ41-000 FFRM-NQ42-000 FFRM-NQ41-DA0 FFRM-NQ42-DA0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO’s goal is to provide you the quickest response possible for your technical support needs. Please visit attotech.com/support for technical support hours.

ATTO Technical Support can be contacted via phone or email:
Phone: 716.691.1999 ext. 242

- E-Mail: techsupport@attotech.com