



ATTO Technology, Inc.

# Product Release Notes

## FastFrame™ 40GbE NIC v1.0.15 – Windows Server 2012 R2, Windows 10, 8.1, and 7 x64.

### 1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the FastFrame 40GbE v1.0.15 Windows release, specifically Windows Server 2012 R2, Windows 10, 8.1, and 7 x64.

### 2. Changes

- **Version 1.0.15 (Released 08/30/2016)**
  - **New Features, Enhancements and Changes**
    - Added Support for Windows 7 and 10
- **Version 1.0.5 (Released 09/17/2015)**
  - **New Features, Enhancements and Changes**
    - Initial release for the FastFrame 40GbE NIC drivers for Windows

### 3. Known Issues/Advisements

- Iperf/nttcp performance in Windows may not display accurate performance figures
- RDMA performance monitor data inconsistent with RDMA testing tool results

### 4. Affected Products

Product Name	SKU
FastFrame 40GbE NICs	FFRM-NQ41-000 FFRM-NQ42-000 FFRM-NQ41-DA0 FFRM-NQ42-DA0

### 5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit [attotech.com/support](http://attotech.com/support) for technical support hours.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)