



## ThunderLink FC 1082 Release v1.00 - Mac OS® X

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 1082 Thunderbolt to Fibre Channel desklink, version 1.00, which was released on 08/13/12. This information pertains to the Mac OS X platform for Intel® based systems.

### 2. Changes

---

- **Version 1.00 (Released 08/13/12)**
  - **New Features, Enhancements and Changes**
    - Initial release for the ThunderLink FC 1082 desklink.

### 3. Known Issues/Advisements

---

- No known advisements.

### 4. Affected Products

---

Product Name	SKU
ThunderLink FC 1082 Desklink Device	TLFC-1082-D00

### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)