



ATTO Technology, Inc.

## Product Release Notes

# ThunderLink Fibre Channel 2082 Multipath Director Release V1.05MP – Mac OS® X

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink Fibre Channel 2082 adapter product v1.05MP that was released on 10/30/2014. This information pertains to Mac OS X. **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.

### 2. Changes

---

- **Version 1.05MP (Released 10/30/2014)**
  - **New Features/Enhancement**
    - Support for Mac OS X 10.10
    - Added support for Quantum StorNext QX series storage.
    - Active/non-optimized paths are activated for I/O in the same manner as standby paths by default.
- **Version 1.00MP**
  - **New Features/Enhancements**
    - Initial release of Mac drivers for the ThunderLink FC 2082.
  - **Supported OS**
    - Mac OS X 10.6.8
    - Mac OS X 10.7
    - Mac OS X 10.8
    - Mac OS X 10.9

### 3. Known Issues/Advisements

---

- None

### 4. Affected Products

---

Product Name	SKU
ThunderLink FC 2082 Desklink device	TLFC-2082-D00

## 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)