



ATTO Technology, Inc.

Product Release Notes

ThunderLink Fibre Channel 2162/2082 Multipath Director Release V1.75MP – Windows

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink Fibre Channel 2162/2082 adapter product v1.75MP that was released on 01/21/16. This information pertains to Windows 10, 8.1, 8, and 7. **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.

2. Changes

- **Version 1.75MP** (01/21/16)
 - **New Features/Enhancements**
 - Resolved a connection issue with previous versions of EMC storage
 - Added limits to the amount of disk space the event log can consume.
 - **Supported OS**
 - Windows 10, 8.1, 8, 7.

- **Version 1.70MP** (08/06/2015)
 - **New Features/Enhancements**
 - Added support for the Dot Hill 4854
 - Feature included when MultiPath Director is enabled and disabled in Device Manager, the devices controlled by it are removed and restored automatically.
 - Fixed a timing issue that could result in removed storage LUNs still being presented to the OS
 - Corrected installation via the Config Tool
 - **Supported OS**
 - Windows 10, 8.1, 8, 7.

- **Version 1.65MP** (03/19/2015)
 - **New Features/Enhancements**
 - Initial release of Mac drivers for the ThunderLink FC 2162 and 2082.
 - **Supported OS**
 - Windows 10, 8.1, 8, 7.

3. Known Issues/Advisements

-
- When interfacing the ATTO ThunderLink 2082 to a 16Gb Fibre Channel switch that uses SFP+ transceivers from Avago (including Avago SPFs re-branded by a switch manufacturer), a link-up delay of up to 60 seconds may be observed if the switch port is set to auto-speed detect. To rectify the delay, set the speed of the interfacing switch port to 8Gb, Avago Part #: 57-000088-01

4. Affected Products

Product Name	SKU
ThunderLink FC 2162 Desklink device	TLFC-2162-D00
ThunderLink FC 2082 Desklink device	TLFC-2082-D00

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit <https://www.attotech.com/support/> for hours of operation.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com