



ThunderLink FC 3162 and 3322 Flash Bundle v170322

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 3162 and 3322 Device flash bundle package, version 170322, which was released on 03/28/17. This information pertains to the flash bundles and BIOS utility associated with the ThunderLink FC products.

2. Changes

- **Version 170322 (Released 03/28/2017)**
 - **New Features, Enhancements and Changes**
 - Initial release of the ThunderLink 3162 and 3322.

3. Known Issues/Advisements

- Currently, no known issues.

4. Affected Products

Product Name	SKU
ThunderLink FC 3162	TLFC-3162-D00/DE0
ThunderLink FC 3322	TLFC-3322-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com