



ATTO Technology, Inc.

Product Release Notes

ThunderLink Fibre Channel 3162/3322 Multipath Director Release V2.05MP – Windows

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink Fibre Channel 3162/3322 adapter product v2.05MP that was released on 03/28/17. This information pertains to Windows Operating systems. **Note:** It is recommended that latest firmware available on ATTO website be utilized with this driver release.

2. Changes

- **Version 2.05MP** (03/28/17)
 - **New Features/Enhancements**
 - Initial release of the ThunderLink 3162 and 3322.
 - **Supported OS**
 - Windows 10, 8.1, 8, 7.

3. Known Issues/Advisements

- Currently, no known issues.

4. Affected Products

Product Name	SKU
ThunderLink FC 3162 device	TLFC-3162-D00
ThunderLink FC 3322 device	TLFC-3322-D00

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit <https://www.attotech.com/support/> for hours of operation.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com