



ThunderLink FC 2082 and 2162 Flash Bundle v150316

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 2082 and 2162 Desklink Devices flash bundle package, version 150316, which was released on 03/25/15. This information pertains to the flash bundles and BIOS utility associated with the ThunderLink FC products.

2. Changes

- **Version 150316 (Released 03/25/2015)**
 - **New Features, Enhancements and Changes**
 - Added support for the FC 2082.
- **Version 140829 (Released 09/02/2014)**
 - **New Features, Enhancements and Changes**
 - Initial release of firmware for ThunderLink FC 2082 and 2162.

3. Known Issues/Advisements

- None

4. Affected Products

Product Name	SKU
ThunderLink FC 2082	TLFC-2082-D00/DE0
ThunderLink FC 2162	TLFC-2162-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com