



## ThunderLink FC 3322 and 3162 Flash Bundle v170322

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 3322 and 3162 and flash bundle package, version 170322, which was released on 04/21/17. This information pertains to the flash bundles associated with the ThunderLink FC products.

### 2. Changes

---

- **Version 170322 (Released 04/21/17)**
  - **New Features, Enhancements and Changes**
    - Initial release of the ThunderLink Fibre Channel 3322 and 3162

### 3. Known Issues/Advisements

---

- No known issues at this time.

### 4. Affected Products

---

Product Name	SKU
ThunderLink FC 3322	TLFC-3322-D00/DE0
ThunderLink FC 3162	TLFC-3162-D00/DE0

### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)