



ATTO Technology, Inc.

Product Release Notes

ThunderLink FC Flash Bundle v190326

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the Fibre Channel ThunderLink and flash bundle package, version 190326, which was released on 3/28/19. This information pertains to the flash bundles associated with the ThunderLink FC products.

2. Changes

- *Version 190326 (Released 03/28/2019)*
 - **New Features, Enhancements, and Changes**
 - Updated flash bundle to latest available version
- *Version 180406 (Released 4/16/2018)*
 - **New Features, Enhancements, and Changes**
 - Added support for a new flash bundle format that supports smaller download portions compatible with the maximum transfer size for the driver
 - Updated firmware version
- *Version 180130 (Released 1/31/2018)*
 - **New Features, Enhancements, and Changes**
 - Updated firmware version
- *Version 171213 (Released 12/18/2017)*
 - **New Features, Enhancements, and Changes**
 - Updated firmware to latest available version
- *Version 170322 (Released 04/21/17)*
 - **New Features, Enhancements and Changes**
 - Initial release of the ThunderLink Fibre Channel 3322 and 3162

3. Known Issues/Advisements

- No known issues at this time.

4. Affected Products

Product Name	SKU
ThunderLink FC 2082	TLFC-2082-D00/DE0
ThunderLink FC 2162	TLFC-2162-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com