



ThunderLink™ FC 2082 and 2162 Release v1.10 - Windows®

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 2082 and 2162 Desklink Devices, version 1.10, which was released on 03/25/15. This information pertains to Microsoft Windows Operating System including Windows 7, 8 and 8.1.

2. Changes

- **Version 1.10 (Released 3/25/15)**
 - **New Features, Enhancements and Changes**
 - Check for FCP_RSP underrun only when the FCP_RSP frame indicates that the RSP_INFO data is present
 - Improvements to allowing incoming PLOGIs in direct P2P after the initialization sequence is complete.
- **Version 1.06 (Released 1/27/15)**
 - **New Features, Enhancements and Changes**
 - Improvements to prevent an exchange leak
- **Version 1.05 (Released 10/30/14)**
 - **New Features, Enhancements and Changes**
 - Corrected an issue where a cable pull could result in I/O failure with MultiPath Director instead of failing over to an alternate path
 - Address resource and performance issues concerning the number of logins being generated by NPIV ports
 - Address a firmware issue causing an error when two or more NPIV ports are querying a switch.
 - Increase the number of Requests (Registry parameter NumRequests) to 3000.
- **Version 1.00 (Released 09/02/14)**
 - **New Features, Enhancements and Changes**
 - Initial release of Windows driver for the ThunderLink FC 2082 and 2162 Desklink Device.
 - Supported OS
 - Windows 7
 - Windows 8
 - Windows 8.1
 - Windows Server 2008 R2
 - Windows Server 2012
 - Windows Server 2012 R2
 -

3. Known Issues/Advisements

- No known advisements.

4. Affected Products

Product Name	SKU
ThunderLink FC 2082	TLFC-2082-D00/DE0
ThunderLink FC 2162	TLFC-2162-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com