



# Product Release Notes

## ThunderLink® FC 3322 and 3162 Release 2.16 - macOS®

### 1. General Release Information

---

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 3322 and 3162 Fibre Channel Thunderbolt Devices, version 2.16, which was released on April 21, 2017. This information pertains to macOS Sierra and later.

### 2. Changes

---

- **Version 2.16 (Released 4/21/17)**
  - **New Features, Enhancements and Changes**
    - Initial release of the ThunderLink Fibre Channel 3322 and 3162

### 3. Known Issues/Advisements

---

- None at this time

### 4. Affected Products

---

Product Name	SKU
ThunderLink FC 3322	TLFC-3322-D00/DE0
ThunderLink FC 3162	TLFC-3162-D00/DE0

### 5. Contacting ATTO Support

---

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)