



ATTO Technology, Inc.

Product Release Notes

ThunderLink® FC 3322 and 3162 Release 2.16 - macOS®

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink FC 3322 and 3162 Fibre Channel Thunderbolt Devices, version 2.16, which was released on April 21, 2017. This information pertains to macOS 10.10 and later.

2. Changes

- **Version 2.16 (Released 4/21/17)**
 - **New Features, Enhancements and Changes**
 - Initial release of the ThunderLink Fibre Channel 3322 and 3162

3. Known Issues/Advisements

- macOS High Sierra has introduced User-Approved Kernel Extension Loading. For additional information on this update, please visit: <http://developer.apple.com/library/content/technotes/tn2459>

4. Affected Products

Product Name	SKU
ThunderLink FC 3322	TLFC-3322-D00/DE0
ThunderLink FC 3162	TLFC-3162-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com