



## ThunderLink™ SH 1068 Release v1.02 - Mac OS® X

### 1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink SH 1068 Desklink™ device, version 1.02, which was released on 11/12/12. This information pertains to the Mac OS X platform for Intel® based systems.

### 2. Changes

- **Version 1.02 (Released 011/12/12)**
  - **Note:** It is recommended that firmware dated 11/09/12 be utilized with this driver release.
  - **New Features, Enhancements and Changes**
    - Initial release for the ThunderLink SH 1068 Desklink device.

### 3. Known Issues/Advisements

- No known advisements.

### 4. Affected Products

Product Name	SKU
ThunderLink SH 1068 Desklink device	TLSH-1068-D00/DE0

### 5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: [techsupport@attotech.com](mailto:techsupport@attotech.com)