



ATTO Technology, Inc.

Product Release Notes

ThunderLink™ SH 3128 Flash Bundle Version 180419

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink SAS Host 3128 flash bundle package which was released on 04/30/18. This information pertains to the flash bundles and BIOS utility associated with the ThunderLink SAS Host products.

2. New Features, Enhancements and Changes

- **Version 180419 (Released 04/30/18)**
 - **New Features, Enhancements and Changes**
 - Initial release of the ThunderLink SH 3128

3. Known Issues/Advisements

Note: Please contact ATTO Technical Support if you need additional information or assistance with these configuration suggestions.

4. Affected Products

Product Name	SKU
ThunderLink SH 3128	TLSH-3128-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com