



ThunderLink™ SH 3128 Flash Bundle Version 190412

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink SAS Host 3128 flash bundle package, released on April 22, 2019. This information pertains to the flash bundles and BIOS utility associated with the ThunderLink SAS Host products.

2. New Features, Enhancements and Changes

- **Version 190412 (Released 04/22/2019)**
 - **New Features, Enhancements and Changes**
 - Incorporated controller firmware 3.09.57
- **Version 180419 (Released 04/30/18)**
 - **New Features, Enhancements and Changes**
 - Initial release of the ThunderLink SH 3128

3. Known Issues/Advisements

None

4. Affected Products

Product Name	SKU
ThunderLink SH 3128	TLSH-3128-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com