



ATTO Technology, Inc.

Product Release Notes

ThunderLink™ SH 3128 Release v1.00- macOS®

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderLink SH 3128, version v1.00, which was released on 04/30/18. This information pertains to the Mac macOS 10.12 and later.

2. Changes

- **Version 1.00 (Released 04/30/18)**
 - **Note:** It is recommended that firmware dated 04/19/18 be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Initial release for the ThunderLink SH 3128

3. Known Issues/Advisements

- The ThunderLink 3128 is currently not interoperable with YoYotta LTFS for macOS
- Pulling thunderbolt cable while writing data may cause driver to not reload
- Note: Please contact ATTO Technical Support if you need additional information or assistance with these configuration suggestions.

4. Affected Products

Product Name	SKU
ThunderLink SH 3128	TLSH-3128-D00/DE0

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 8:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com