



ATTO Technology, Inc.

Product Release Notes

ThunderStream™ SC 3808D Release v1.02 - Mac OS® X

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderStream SC 3808D RAID Storage Controller Desklink™ device, version 1.02, which was released on 09/26/12. This information pertains to the Mac OS X platform for Intel® based systems.

2. Changes

- **Version 1.02 (Released 09/26/12)**
 - **Note:** It is recommended that firmware dated 08/09/12 be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Updated the memory allocation for x64 platforms for compatibility with OS X 10.8.2 and later.
 - A notification will be sent that the firmware has been reset when coming out of power management.
 - Improved the device polling based on the Device Wait Time and Count settings to prevent device thrashing on power up and sleep recovery.
 - Added support for Frey B2 chips.
- **Version 1.01 (Released 08/13/12)**
 - **Note:** It is recommended that firmware dated 08/09/12 be utilized with this driver release.
 - **New Features, Enhancements and Changes**
 - Initial release for the ThunderStream 3808D Desklink device.

3. Known Issues/Advisements

- No known advisements.

4. Affected Products

Product Name	SKU
ThunderStream SC 3808D Desklink device	TSSC-3808-D00

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com