



ATTO Technology, Inc.

Product Release Notes

ThunderStream™ SC 4808D Flash Bundle Version 150203

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ThunderStream RAID Storage Controller 4808 Desklink Device flash bundle package which was released on 02/23/15. This information pertains to the flash bundles and BIOS utility associated with the ThunderStream RAID Storage Controller products.

2. Changes

- **Version 15_02_03 (Released 02/23/15)**
 - **New Features, Enhancements and Changes**
 - Initial release of the ThunderStream 4808

Known Issues/Advisements

Note: Please contact ATTO Technical Support if you need additional information or assistance with these configuration suggestions.

- There is an interoperability issue with Toshiba MK2002TSKB 3Gbps SATA drives. A workaround for the issue is to disable NCQ.

3. Affected Products

Product Name	SKU
ThunderStream SC 4808D Desklink Device	TSSC-4808-D00/DE0

4. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs, and is available Monday-Friday, 8:00 AM to 6:00 PM EST (except holidays and plant closings).

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com