



ATTO Technology, Inc.

Product Release Notes

ATTO 360™ Tuning, Monitoring, and Analytics Software

1. General Release Information

These product release notes define the new features, changes, known issues and release details that apply to the ATTO 360™ Tuning, Monitoring, and Analytics Software that was released on December 18th 2019. This information pertains to the following operating systems: macOS®, Windows®, and Linux

2. Changes

- **Version 1.00 (Released 12/18/2019)**
 - **New Features/Enhancements**
Initial Release

3. Known Issues/Advisements

- On the macOS® version initiating tuning profiles can sometimes cause SMB shares to unmount, we recommend unmounting SMB shares before running tuning profiles.
- Adjusting MTU sizes can cause 360 to freeze, restart 360 to continue using

4. Affected Products

Product Name	SKU
FastFrame3 N322	FFRM-N322-DA0
FastFrame3 N351	FFRM-N351-DA0
FastFrame3 N352	FFRM-N352-DA0
FastFrame3 N311	FFRM-N311-DA0
FastFrame3 N312	FFRM-N312-DA0
Thunderlink 3102	TLN3-3102-000
Thunderlink 3252	TLNS-3252-000

5. Contacting ATTO Support

ATTO Technology, Inc. is renowned for its technical support services. ATTO's goal is to provide you the quickest response possible for your technical support needs. Please visit <https://www.attotech.com/support/> for hours of operation.

ATTO Technical Support can be contacted via phone or email:

- Phone: 716.691.1999 ext. 242
- E-Mail: techsupport@attotech.com